

Testing and Consultancy Work (2023-24)

S.No.	PI name	Co-PI names if any	Name of the Dept., where project is sanctioned	Project title*	Name of the Funding agency	Duration of the project (days)	Amount (Lacs)
1	Prof. Sunil K. Ahirwar, Prof. Tarun Narnaure		CE-AMD	Basalt Testing and Consultancy	South Central Railway	2023-24	0.84
2	Prof. Sunil K. Ahirwar, Prof. Devendra Dohare	Prof. Vivek Tiwari, Prof. Tarun Kumar Narnaure	CE-AMD	Concrete Mix Design		2023-25	0.18
3	Dr. S. M. Narulkar, Dr. H. K. Mahiyar	Dr. Sunil K. Ahirwar, Prof. Devendra Dohare, Vivek Tiwari, Tarun Kumar Narnaure	CE-AMD	Concrete Testing		2023-26	1.03
4	Prof. Tarun Kumar Narnaure		CE-AMD	Filter Media Testing		2023-27	0.04
5	Dr. S. M. Narulkar, Dr. H. K. Mahiyar	Prof. Vivek Tiwari, Prof. Tarun Kumar Narnaure	CE-AMD	Material Testing and Consultancy		2023-28	1.34
6	Dr. S. M. Narulkar, Dr. S. B. Ajmera	Dr. Sunil K. Ahirwar, Prof. Devendra Dohare, Vivek Tiwari, Tarun Kumar Narnaure	CE-AMD	Paver block Concrete testing		2023-29	2.71
7	Dr. H. K. Mahiyar, Prof. M. K. Laghate, Sunil K. Ahirwar	Prof. Vivek Tiwari, Prof. Tarun Kumar Narnaure	CE-AMD	Soil Testing and Investigation		2023-30	7.85
8	Prof. Devendra Dohare		CE-AMD	Water Parameter Testing		2023-31	0.27
9	Dr. S. M. Narulkar, Dr. H. K. Mahiyar	Dr. Sunil K. Ahirwar, Prof. Devendra Dohare, Vivek Tiwari, Tarun Kumar Narnaure	CE-AMD	Mix Design		2023-32	29.9
10	R. K. Khare	Vivek Tiwari	CE-AMD	Proof checking of structural drawing (with necessary calculation and details) of Firing Range Structures	MP Police Housing Indore	32	0.5428
11	Sunil Kumar Ahirwar		CE-AMD	Pile Load Test Report	CPWD Indore Sanjay Jain	5	0.21712
12	S. B. Ajmera	Prof. Devendra Dohare	CE-AMD	Checking of water supply DPR of Niwali Town	CMO Nagar Parishad, Niwali Bujurg	10	1.01775
13	R. K. Khare,	Sunil Ahirwar and Vivek Tiwari	CE-AMD	CAC/CAP/05/2021-22 Provision of four Igloos storage of armament store as per CWR at AF STN, Gwalior	Mohit Goyal EE GO (AP) MES Gwalior	21	0.33925
14	R. K. Khare	Vivek Tiwari	CE-AMD	Site visit, material testing and consultancy advise reg delapidated/Tattered/damaged residential constable quarters (8+18), DRP Line Khargone M.P.	MP Police Housing Indore	52	2.4426

15	S. M. Narulkar	Vivek Tiwari	CE-AMD	Reg Inspection of Balwasa Barrage	EE WRD No. 1 Jhabua Jain Engg.	65	0.4071
16	Vijay Rode,	M.K. Laghate and Vivek Tiwari	CE-AMD	Site visit report of Arch Bridge over Narmada River in Indore-Khandwa Route situated near Mortakka Village	Prsoject Director NHAH Indore	57	0.6095
17	Vijay Rode,	M.K. Laghate and R. K. Khare	CE-AMD	Proof checking of detailed structural drawing and design of small ETP and STP Plant with Pump Room Civil Hospital Indore and Dewas	Aadharshila	68	0.6785
18	M.K. Laghate	S.K. Ahirwar	CE-AMD	Site Visit of "Masonry Building No. 22/10 (old 32/10) situated in zone -17, ward-23 Pardeshipura, Indore" for building structural audit	IMC Indore Zone No. 17 Narwal Zone	39	0.33926
19	R. K. Khare,	M.K. Laghate and Vivek Tiwari	CE-AMD	Vetting of structural design and drawing of Piles, Pile Cap and Pier 10 Nos of Flyover at Bhawarsla (Luvkush) square along MR 10 Rd and Supercorridor, Indore M.P.	EE IDA Indore	177	3.105
20	S. M. Narulkar	S. B. Ajmera	CE-AMD	Consultancy report reg site visit report of Natnagara talab	CMO Nagar Parishad, Dhar	0	0.4071
21	S. M. Narulkar	Vivek Tiwari	CE-AMD	Site visit and NDT testing report of LIG Building IDA Scheme No. 54 Indore	EE PHE Musakhedi Indore	87	0.4071
22	S. M. Narulkar,	S.B. Ajmera and S. K. Ahirwar	CE-AMD	Consultancy report regarding site visit report of retaining wall	Nagar Parishad Karhi-Padlyakhurd Khargone	199	4.1071
23	S. K. Ahirwar		CE-AMD	Pile Load Test Report	CPWD Indore	142	0.21712
24	R. K. Khare		CE-AMD	Checking of design and drawing of RCC 20,000 litre/hour electric operated fluoride removable community water treatment plant at village dehari, Block kushki of Dist DHAR, M.P.	Wist Water Solution Pvt. Ltd. Kilkata	14	0.33925
25	S. K. Ahirwar		CE-AMD	Lateral Pile Load Test Report	CPWD Indore Sanjay Jain	0	0.48
26	S. M. Narulkar	S.B. Ajmera and S. K. Ahirwar	CE-AMD	Stability Check and quality testing for under construction barage, nagar parishad, kumbhraj	Nagar Parishad Kumbhraj Distt.Guna	255	0.5428
27	S. M. Narulkar	Dr. S.B. Ajmera, Dr. S. K. Ahirwar	CE-AMD	Checking for design of Retaining Wall divided into two portion, one of length 300 mtr and second 250 m at Karhi-Padliya khurd distt Khargone M.P.	Nagar Parishad Karhi-Padlyakhurd Khargone	26	0.9499

28	S. M. Narulkar	Dr. S. K. Ahirwar	CE-AMD	Checking of structural design of retaining wall for S.D.M.F scheme	CMO Nagar Parishad Omkareshwar, Khandwa	357	0.4071
29	S. M. Narulkar	Dr. S. K. Ahirwar	CE-AMD	Site Visit of RCC Nalla's structural drawing design for S.D.M.F. scheme	CMO Nagar Parishad Omkareshwar, Khandwa	7	0.4071
30	R. K. Khare	Prof. Vivek Tiwari	CE-AMD	NDT report of structural stability checking and inspection of old Over Head Tank of Income Tax Colony, Residency Area, Indore M.P.	AE CPWD Division 1 Indore	130	0.5428
31	Vijay Rode	Prof. M. K. Laghate	CE-AMD	Drawing and Design of Pump House 1 of Micro Irrigation system for Samaakota Barrage Pariyojna	EE Water Resources M/s. Goodwill	31	1.357
32	Vijay Rode	Prof. M. K. Laghate, Prof. Vivek Tiwari	CE-AMD	load test of Arch Bridge over Narmada River situated near Mortaka Village on Indore Khandwa route	Project Director, NHAI Indore	112	5.428
33	Vijay Rode	Prof. Vivek Tiwari	CE-AMD	Site visit and NDT testing report of LIG Building IDA Scheme No. 54 Indore	IDA Indore	202	0.7314
34	Vijay Rode	Prof. Vivek Tiwari	CE-AMD	Vetting of structural design and drawing of Botany Lab PG College, Khargone	EE MP HB I DB Khandwa	197	0.5428
35	R. K. Khare	Dr. S. B. Ajmera	CE-AMD	Building Safety certificate after due inspection and visual rapid screening	Delhi Public School, Indore	7	2.714
36	R. K. Khare	Dr. R. K. Khare, Prof. Vivek Tiwari, Prof. Tarun Kumar Narnaure	CE-AMD	Testing of construction work of upgradation of 6 bed medical facility to 30 bed community health centre at block bhagwanpur dist Khargone	EE Building P.W.D. Khargone	225	2.46974
37	S. M. Narulkar	Dr. S. K. Ahirwar	CE-AMD	Site visit for checking the strength of wall of sitaram jaju sagar dam	CMO Nagar Palika Parishad, Neemuch	33	0.5428
38	R. K. Khare	Prof. M. K. Laghate	CE-AMD	Proof checking of design and approval drawing of PEB Structure for Shrewsbury Int. School India, Mungaliachhap Bhopal M.P. (Jagran Social Welfare Society)	P.F.P.L. C/o Jagrn Social Welfare Society	6	1.357
39	M. K. Laghate	Prof. Tarun Kumar Narnaure	CE-AMD	NDT of administration office having cracks situated at YN Rd Indore	Chief Manager, SBI Indore	85	0.8142
40	Vijay Rode	Dr. R. K. Khare, Prof. M. K. Laghate, Prof. Vivek Tiwari	CE-AMD	Proof checking of structural drawing and design of commercial building (City Palace Mall), Burhanpur	Rajkumar Gupta LLP Khandwa	178	5.5637
41	Vijay Rode	Prof. M. K. Laghate	CE-AMD	Site visit for inspection of Over Head water tanks near Saket Club, Indore	EE Lok Swastha Yantiriki Khand No. 2, Indore	51	0.5428

42	S. M. Narulkar	Prof. M. K. Laghate, Prof. Tarun Kumar Naunaure	CE-AMD	site visit for inspection of Two-lane 270 meter long box bridge by 30 meters fan located at PIU Rathlam Advaniya Chandigarh to Bajna Banswada Road damage during September 2023 flood	GM MPRRDA Ratlam MP	62	1.3571
43	S. M. Narulkar	Prof. M. K. Laghate, Prof. Tarun Kumar Naunaure	CE-AMD	Rapid vishal screening for Navlakha Complex building at Indore	Indore Development Authority Indore	40	6.785
44	S. M. Narulkar	Dr. S. B. Ajmera	CE-AMD	Approval Drawing and design of barrage and earthen dam of samakota barrage	EE Water Resources Devision Ujjain Goodwill	141	8.142
45	R. K. Khare	Prof. M. K. Laghate	CE-AMD	Checking of design and drawing of unfold hoarding at Jaoara compound site Indore MP	ZIVAH Pvt. Limited	29	0.38924
						Total	101.40303